


Probability Plot for 15

Normal - 95% CI




Goodness of Fit Test

Normal
AD = 0.888
P-Value = 0.022

Probability Plot for 20

Normal - 95% CI




Goodness of Fit Test

Normal
AD = 0.789
P-Value = 0.039

Probability Plot for 25

Normal - 95% CI




Goodness of Fit Test

Normal
AD = 0.385
P-Value = 0.387

Probability Plot for 30

Normal - 95% CI



Goodness of Fit Test

Normal
AD = 0.562
P-Value = 0.142